



Ram eco diesel 52k



Excessive build-up on the EGR cooler and manifold can lead to thermal cracking of components.

If this goes unaddressed it can lead to costly repairs upwards of \$8000.

