

Actual Claim - Brake

Claim Info

Type LPP
Status Paid
Reported Date Jun 27, 2017
Last updated Jun 27, 2017
Authorization Number 2017062713399

Current Owner

Current Owner
Address
City North Attleboro
State | Province | Region MA
Postal Code 02760
Phone

Vehicle

Vehicle ID 216803
Vehicle 2010 Land Rover Range Rover Sport
VIN

Repair

Service Name Brake Service	Resolution Description REPLACE R/F CALIPER
Service Date Jun 27, 2017	Service Locations JAKE KAPLANS JAGUAR RR 1346 BALD HILL ROAD WARWICK , RI 02886
Service Odometer 52,071	Repair Locations Same as service location.
Failed Component Brakes	
Time of Failure 52,071	
Time of Repair 52,071	
Original Complaint EXCESSIVE NOISE, BRAKE LIGHT ON	

Service History

Service Date Jun 27, 2017
Service Name Brake Service
Odometer 52,071

Service Date Aug 24, 2015
Service Name Brake Service
Odometer 43,887

Expenses

Materials & Parts	1145.06
Labor	148.00
Tax	80.15
Administration Fee	0.00
Inspection Fee	0.00
BG Claim Payout	1373.21
Payment Type	Epm
Repair Date	-
Total Repair Cost	1373.21
Total Plan Expense	1373.21
Owner Cost	0.00

Retail Customer

PAYS:

**1 Brake Fluid Exchange
Service Retail = \$139.95**

GETS:

**\$139.95 investment brought the
customer a \$1373.21 return or a
881% return on investment.**
