

# Actual Claim - Drive Line

---

## Claim Info

---

**Type** LPP  
**Status** Paid  
**Reported Date** Aug 19, 2016  
**Last updated** Aug 19, 2016  
**Authorization Number** 2016081910176

---

## Current Owner

---

**Current Owner**  
**Address**  
**City** Rochester  
**State | Province | Region** NH  
**Postal Code** 03867  
**Phone**

---

## Vehicle

---

**Vehicle ID** 156819  
**Vehicle** 2007 Pontiac Solstice  
**VIN**

---

## Repair

---

**Service Name** Drive Line Service  
**Service Date** Aug 19, 2016  
**Service Odometer** 31,611  
**Failed Component** Rear Differential  
**Time of Failure** 31,611  
**Time of Repair** 31,611

**Original Complaint** cust states rear end is making a grinding noise and hopping when taking slow corners or down shifting  
**Resolution Description** needs rear differential and fluids  
**Service Locations** Midway Buick GMC  
Rte 108  
Somersworth, NH 03878  
**Repair Locations** Same as service location.

---

## Service History

---

**Service Date** Aug 19, 2016  
**Service Name** Drive Line Service  
**Odometer** 31,611

**Service Date** Oct 26, 2011  
**Service Name** Drive Line Service  
**Odometer** 24,336

---

## Expenses

---

<b>Materials &amp; Parts</b>	2315.79
<b>Labor</b>	460.00
<b>Tax</b>	0.00
<b>Administration Fee</b>	0.00
<b>Inspection Fee</b>	0.00
<b>BG Claim Payout</b>	2775.79
<b>Payment Type</b>	Ccm-credit-card
<b>Repair Date</b>	-
<b>Total Repair Cost</b>	2775.79
<b>Total Plan Expense</b>	2775.79
<b>Owner Cost</b>	0.00

## Retail Customer

### **PAYS:**

**1 Drive Line Service @ \$99.95**

### **GETS:**

**\$99.95 investment brought the customer a \$2,776 return or a 2,776% return on investment.**