

Actual Claim - Drive Line

Claim Info

Type LPP
Status Paid
Reported Date Aug 19, 2016
Last updated Aug 19, 2016
Authorization Number 2016081910176

Current Owner

Current Owner
Address
City Rochester
State | Province | Region NH
Postal Code 03867
Phone

Vehicle

Vehicle ID 156819
Vehicle 2007 Pontiac Solstice
VIN

Repair

Service Name Drive Line Service
Service Date Aug 19, 2016
Service Odometer 31,611
Failed Component Rear Differential
Time of Failure 31,611
Time of Repair 31,611

Original Complaint cust states rear end is making a grinding noise and hopping when taking slow corners or down shifting
Resolution Description needs rear differential and fluids
Service Locations Midway Buick GMC
Rte 108
Somersworth, NH 03878
Repair Locations Same as service location.

Service History

Service Date Aug 19, 2016
Service Name Drive Line Service
Odometer 31,611

Service Date Oct 26, 2011
Service Name Drive Line Service
Odometer 24,336

Expenses

Materials & Parts	2315.79
Labor	460.00
Tax	0.00
Administration Fee	0.00
Inspection Fee	0.00
BG Claim Payout	2775.79
Payment Type	Ccm-credit-card
Repair Date	-
Total Repair Cost	2775.79
Total Plan Expense	2775.79
Owner Cost	0.00

Retail Customer

PAYS:

1 Drive Line Service @ \$99.95

GETS:

\$99.95 investment brought the customer a \$2,776 return or a 2,677% return on investment.