

HITACHI

1. Inspire the Next

After an extensive testing program, and with the cooperation of our **BG Distributors in Japan**, we are pleased to confirm that Hitachi Machinery Construction Co. Ltd., Japan, has issued a Service Bulletin (Code number 3 204 0234A) that recommends **the BG Diesel Injection Service**. The Bulletin specifically references all ZX120-3/5B and ZX350-3/5B units. We cannot provide the Service Bulletin as it is a confidential document, however Hitachi dealers will be able to locate it from the code above.

In addition, the Company has given Hitachi Genuine Part Numbers to the products, tools and equipment as referenced below. The local dealer should be able to reference these in the Hitachi procurement system.

<u>BG Items</u>	<u>Hitachi Genuine Part Number</u>
BG Diesel Care, PN BG22932	YA00040184
BG DFC Plus HP, PN BG23232	YA00040185
BG Diesel VIA, PN BG9700-550	YA00040186
BG Filter, PN BG9700-020	YA00040187



2. FUSO

Following an initial Japan-based recommendation for the **BG Diesel Injection Service**, issued by (Daimler) Mitsubishi Fuso in 2007, we are pleased to announce that the recommendation now applies globally and Mitsubishi Fuso has entered new Genuine Part Numbers to its procurement system. The Fuso Service Bulletin, Code number 06T-016, references all small and medium size trucks, as well as all small and large size buses equipped with 4M4 or 4M5 engines. The (global) Genuine Part Numbers are as follows:

<u>BG Items</u>	<u>Mitsubishi Fuso Genuine Part Number</u>
BG Diesel Care, PN BG22932	QZ000680
BG Diesel Fuel Cleaner, PN BG244	QZ000681
BG Diesel VIA, PN BG9700-550	QZ000682
BG Filter, PN BG9700-020	QZ000683

For both the Hitachi and Mitsubishi Fuso recommendations, the BG Diesel Injections Service is recommended as needed and before any injectors are replaced.